A330

A/C Type : Flight Phase : Classification : Events:

Climb

Climb
Occurrences
Lightning Strike
A/c Equipment / System
Failure
A/c Equipment / System
Malfunction

## Pretitle:

Aircraft experienced two lightning strikes during the climb.

Precis:

Systems unaffected, except for both HF transceivers failing and the standby compass indicating a 30deg error. Following arrival, inspection revealed several exit holes along the RH side.

Occurrence Number :

Occurrence Date :

Location Info :

200303372 01 Jun 2003 Dalaman